VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestid/Import Vehicles

CAMPAIGN No.	2848	DATE	Nov 9, 2011		
MANUFACTURER	TOYOTA MODELLISTA INTERNATIONAL CO.				
DESCRIPTION OF	In the welfare vehicles for commercial use equipped with an electrical sliding				
	door, a necessary empty space between the platform and the rear seating				
	position, which is prescribed in the aisle requirement of Safety Regulation				
	Section 23.2, is not secured.				
DEFECT					

TYPE NAME YEAR RECALLED VEHICLE OBF-TRH200K"kai" (modified) HIACE REGIUS ACE N/A 3 ADF-KDH201K"kai" (modified) HIACE REGIUS ACE N/A 3		COMMERCIAL	M	ODEL	NUMBER OF
CBF-TRH200K "kai" (modified) HIACE REGIUS ACE N/A 3 ADF-KDH201K "kai" (modified) 2	ТҮРЕ	NAME	Y	'EAR	VEHICLE
ADF-KDH201K "kai" (modified) 2			REC	ALLED	
	CBF-TRH200K"kai"(modified)	HIACE REGIUS ACE		N/A	3
	ADF-KDH201K"kai"(modified)				2
TOTAL 5					
TOTAL 5					
TOTAL 5					
TOTAL 5					
TOTAL 5					
TOTAL 5					
TOTAL 5					
TOTAL 5					
				TOTAL	5