

# VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

~~Domestic~~ / Import Vehicles

CAMPAIGN No.	Gai-1796	DATE	November 28, 2011
MANUFACTURE	Automobiles CITROËN Automobiles PEUGEOT (Japanese Importer : PEUGEOT CITROËN JAPON Co.,Ltd.)		
DESCRIPTION OF DEFECT	On an engine room electrical harness system, the dimensional non-conformity of the battery earth cable may lead in the long-term to its breakage due to the excessive tension. As the loss of this electrical connection may lead to the engine cutting out.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-A75F01 ABA-A7C5F01 ABA-A7W5F01	PEUGEOT 207 PEUGEOT 207CC PEUGEOT 207SW	2011	1110
ABA-A55F01 ABA-A5C5F01	Citroën C3 Citroën DS3	2010-2011	627
		TOTAL	1737