

**Form No. 4: Summary of Recall Campaign in English (Related to Article 2)**

**Vehicle Safety/Pollution Recall Campaign in Japan**

Import Vehicles

Campaign No.	Gai - 1817	Date	March,5,2012
Manufacturer	Land Rover Group Limited Japanese Importer: Jaguar Land Rover Japan Limited		
Description of defect	<p>A concern has been identified with certain Range Rover, Range Rover Sport and Discovery 4 vehicles in Japan where the proximity camera images may not be displayed and an error screen shown as a white camera icon crossed out on a blue background on the centre display screen. This may occur when selecting reverse gear, forward gear for the first time after engine start or selecting the camera home page. This can be an intermittent or permanent condition within an ignition cycle.</p> <p>Japan's Ministry of Land, Infrastructure and Transport's Safety Regulations for Road Vehicles require certain vehicles to have a device to show enhanced visibility requirements. Vehicles included in this compliance recall employ a five camera system, the front left and left mirror cameras are used to provide the vision field as prescribed by Japanese regulation for Proximity front/side visibility requirements. One or both of these cameras may cause a white camera icon crossed out on a blue background on the centre display screen, therefore not providing the necessary images in order to comply with the regulation.</p>		

Type	Commercial name	Model year recalled	Number of vehicles
ABA-LA5N	Discovery 4	2010 - 2011	325
ABA-LS5N	Range Rover Sport 5.0 V8	2010 - 2011	315
ABA-LS5S	Range Rover Sport SUPERCHARGED	2010 - 2011	57
ABA-LM5N	Range Rover Vogue 5.0 V8	2010	100
ABA-LM5S	Range Rover Vogue SUPERCHARGED	2010 - 2011	50
Total			847

(JIS A4 size)