

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	2920	DATE	Apr.11.2012
MANUFACTURER	TOYOTA		
DESCRIPTION OF DEFECT	In welfare vehicles for commercial use, the requirement space in the aisle to the rear seat, which is prescribed in the aisle requirement of Safety Regulation Section 23. 2, is not secured.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	NOTE
CBF-TRH223B “kai”(modified)	HIACE REGIUS ACE	2005-2012	84	#1
CBF-TRH228B “kai”(modified)		2005-2011	13	
KR-KDH222B “kai”(modified)		2005-2007	5	
ADF-KDH223B “kai”(modified) LDF-KDH223B “kai”(modified)		2008-2011	28	
KR-KDH227B “kai”(modified)		2005-2007	15	
CBF-TRH200K “kai”(modified)		2004-2012	508	
KR-KDH200K “kai”(modified)	2004-2007	42		
ADF-KDH201K “kai”(modified) LDF-KDH201K “kai”(modified)	2007-2012	51		
KR-KDH205K “kai”(modified)	2004-2007	39		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	NOTE
ADF-KDH206K "kai"(modified) LDF-KDH206K "kai"(modified)	HIACE REGIUS ACE	2007-2012	49	#2
TOTAL			834	

#1 145

#2 689