

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	2929	DATE	Apr. 24 2012
MUNUFACTURER	Mitsubishi Fuso Truck and Bus Corporation		
DESCRIPTION OF DEFECT	On some heavy-duty trucks, the exhaust pipe (front pipe) is improperly welded. If the vehicle continues to be used in this condition, the welds may crack resulting in a break.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
LKG-FU54VZ	FUSO	2010~2012	77
QKG-FU54VZ		2012	1
		TOTAL	78