

## VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	Gai-1882	DATE	2012/11/15
MANUFACTURE	Daimler AG (Japanese Importer : Mercedes-Benz Japan Co., Ltd. )		
DESCRIPTION OF DEFECT	Due to an improper shape of the all weather floor mats and ribbed floor mats which are sold as genuine accessories, in case that these floor mats are installed, temporary contact between the floor mat and the accelerator pedal may be happened and the accelerator pedal may possibly be released with a delay. For this extremely unlikely case, unintentional acceleration might be continued, however, there is a guarantee that the driver can safely brake the vehicle to a standstill at any time using the standard "Brake Override System" with even just slight pedal force - irrespective of the accelerator pedal position.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
RBA-166057	ML350	2012	7
		TOTAL	7