

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

~~Domestic~~ / Import Vehicles

CAMPAIGN No.	3053	DATE	12/19/ 2012
MANUFACTURE	MITSUBISHI HEAVY INDUSTRIES,LTD.		
DESCRIPTION OF DEFECT	The location of the operation switch of the defroster does not adapt to the Safety Standard of the Road Trucking Vehicle Act.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
RS450	MITSUBISHI REACH STACKER	2007 ~ 2012	2
		TOTAL	2