

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/ Vehicles

CAMPAIGN No.	3084	DATE	Jan. 30th, 2013
MANUFACTURER	Yokohama Sharyo Kogyo Co.,Ltd.		
DESCRIPTION OF DEFECT	The geometric visibility at upper portion of inside the reflector does not conform against the safety standard of road haulage vehicle, because the large sized rear reflector has been attached with unsuitable position designed for the exclusive usage vehicle to carry the container body.		
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
LKG-CYY77AY	GIGA	2012	9
QKG-CYY77AY	GIGA	2012~2013	15
		TOTAL	24