

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

Campaign No.	Gai-1896	Date	January 29, 2013
Manufacturer	BOMAG GmbH (Japanese importer: KOBELCO CONSTRUCTION MACHINERY CO., LTD.)		
Description of Defect	<p>The insert nut for drain plug is embedded onto the fuel tank made by resin. Due to its improper bonding and sealing structure with the drain plug, the insert nut will be rotated together with the drain plug by tightening force when tightening or loosening the drain plug. This will cause the deterioration of sealing ability.</p> <p>Because of this, fuel may leak when the machine is continued to be operated as it is.</p>		

Type	Commercial name	Model year recalled	Number of Vehicles
—	BW115AC-3	2011 - 2012	89
	BW115AD-3	2011	3
	BW131ACW-3	2011 - 2012	70
	BW131AD-3	2010	1
		2012	1
		Total	164