

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

Campaign No.	3088	Date	27th February ,2013
Manufacture	CATERPILLAR JAPAN LTD.		
Description of Deffect	Fuel filter base pipe would leak fuel. Filter base was damaged by pipe at assembly process.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
KDP-SAT	「910H」	2007-2009	252
		TOTAL	252