

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3 1 3 8	DATE	Apr.4.2013
MANUFACTURER	N I S S A N		
DESCRIPTION OF DEFECT	<p>On the emergency vehicles, the durability of the plastic band securing the battery cable was insufficient. The plastic band may break. As a result, the battery cable will touch the exhaust tube. In an extreme case, the battery cable may cause a short circuit and the engine may stall during the driving.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
E-ALE50(KAI)	N I S S A N CARAVAN ELGRAND	1 9 9 8 ~ 2 0 0 9	37
GE-FLGE50	N I S S A N PARAMEDIC		209
TC-FPGE50 ABF-FPGE50 CBF-FPGE50			174
E-JALE50(KAI)	I S U Z U FARGO FILLY	1 9 9 9 ~ 2 0 0 1	2
GE-JFLGE50	I S U Z U SUPER MEDIC II		12
		TOTAL	434