

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

~~Domestic~~ / Import Vehicles

CAMPAIGN No.	3114	DATE	3/6/ 2013
MANUFACTURE	MITSUBISHI HEAVY INDUSTRIES,LTD.		
DESCRIPTION OF DEFECT	The location of the operation switch of the windshield wiper does not adapt to the Safety Standard of the Road Trucking Vehicle Act.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
F14C	「MITSUBISHI FORKLIFT」	1999 ~ 2003	1
F19C			1
		TOTAL	2