

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	3134	DATE	March 27,2013
MANUFACTURER	KYOKUTO KAIHATSU KOGYO CO. LTD.		
DESCRIPTION OF DEFECT	<p>In the detachable body trucks equipped with the parking brake of center brake type, there are some vehicles that have improper clearance between the parking brake wire and the fastener parts (chassis frame supporter) to fix the detachable body mechanism to the chassis frame. Therefore, in case of keeping using the vehicle as it is, it can cause damage the parking brake wire due to contact the parking brake wire with the fastener parts, at worst, there is not only cut the parking brake wire but also threaten to be malfunction of the parking brake.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
PKG-FRR90S2	FORWARD	2007-2010	10
PKG-FSR90S2	FORWARD	2007,2009	2
SKG-FRR90S2	FORWARD	2012	3
SKG-FSR90S2	FORWARD	2011	1
TKG-FRR90S2	FORWARD	2012	2
TOTAL			18