

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	3182	DATE	June 27, 2013
MANUFACTURER	KYOKUTO KAIHATSU KOGYO CO., LTD.		
DESCRIPTION OF DEFECT	<p>On Refuse compactor trucks equipped with the modified exhaust pipe of the T-shaped opening mouth, by reason of being an inadequate direction of exhaust pipe opening mouth does not violated safety standard of road trucking vehicle (It shall not be inclined more than 30 degrees at vertical plane included center line of vehicle).</p> <p>As a remedy for countermeasure, all intended vehicles will be exchanged the exhaust pipe (tail pipe) for the countermeasure parts and the insulator (heat protection plate) will be installed.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
BJG-XKU304A	TOYOTA DYNA	2010	1
BDG-XZU304A		2010	1
BJG-XKU304X	HINO DUTRO	2010	1
BDG-XZU304X		2010	1
BKG-XZU304E		2010	1
BDG-XZU404M		2010, 2012	2
BDG-XZU404X		2010	1
BKG-XZU404M		2010	1
BDG-XZU414M		2010	2
		TOTAL	