

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-1957	DATE	20 th August 2013
MANUFACTURE	Triumph Motorcycles Limited (Japanese Importer : Triumph Japan K.K.)		
DESCRIPTION OF DEFECT	Aluminum filings were generated during production and remained inside the product which could potentially grind the seal part of the outlet check valve when the ABS is operated causing the functional capability of the seal to be lost along with the functional capability of the ABS. There could be friction between the body and the check valve due to misaligned press fitting of the check valve due to which the body end-face could break and aluminum filing could be generated.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
LX	Street Triple	2013	118
		TOTAL	118