

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic ☒ Import Vehicles

CAMPAIGN No.	Gai-1962	DATE	Sep. 25. 2013
MANUFACTURE	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	The threaded fasteners of the luggage carrier (optional accessory) to lose their preload and in the course of time these fasteners can work loose. If this is not noticed by the rider the luggage carrier, complete with the components mounted on it (e.g. top-case), can become detached from the vehicle.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
C650GT	BMW C650GT	2012-2013	356
		TOTAL	356