

VEHICLE SAFETY/ POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicle

| | | | |
|-----------------------|--|------|--------------------|
| CAMPAIGN No. | 3224 | DATE | September 12, 2013 |
| MANUFACTURER | Komatsu Ltd. | | |
| DESCRIPTION OF DEFECT | In some circuit breakers used to shut off the electrical currents in electrical circuits when abnormality occurs, cable terminals were bent when they were installed because of improper assembly instruction for those terminals. Accordingly, if one of those circuit breakers is used as it is, the terminals generate heat. In the worst case, the circuit breaker shuts off the electric currents in the electrical circuits and the machine cannot travel. | | |

| TYPE | COMMERCIAL NAME | MODEL YEAR RECALLED | NUMBER OF VEHICLE |
|--------|-----------------|---------------------|-------------------|
| HV3000 | 「HV3000-1」 | 2000~2008 | 18 |
| HV6000 | 「HV6000-1」 | 2001~2008 | 38 |
| | | TOTAL | 56 |