VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN Domestic/Import Vehicles

CAMPAIGN No.	3209	DATE	September. 4. 2013	
MANUFACTURER	HANTA MACHINERY CO. LTD.			
DESCRIPTION OF DEFECT	There is potential danger that fuel filter which is equipped on engine of asphalt pavers cause pipe coupling loosening and fuel leakage due to decreasing the strength of pipe coupling by aging degradation.			

ТҮРЕ	COMMERCIAL	MODEL YEAR	NUMBER OF
	NAME	RECALLED	VEHICLE
SB- F40W2	F 45W	2006~2009	325
KDN- F 4 5 W 3	F 45W3	2009~2013	131
KDN- A45WB	HA45W-7	2009~2013	298
		TOTAL	754