

# VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

(Domestic) Import Vehicles

CAMPAIGN No.	3174	DATE	July 12, 2013
MANUFACTURER	NIPPON TREX CO., LTD. 350 Minamiyamashinden, Ina-cho, Toyokawa city, Aichi prefecture, Japan		
DESCRIPTION OF DEFECT	For Bulk carrier trailer (with three axle) under the Deregulation of Trailer GVW for Separatable Cargo under the Safety Regulation of laws of Japan, when running the vehicle, stresses will concentrate onto subframe since evaluation of subframe strength is inadequate. If the trailer is kept used under this condition, continuous stress, which is generated by running the vehicle, would make the crack to appear in the frame, and thus can decrease strength of the vehicle.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
TNF325AA	—	2011	1
TNF325AB	—	2011	1
TNF325AC	—	2011	2
TNF325AD	—	2011~2012	5
TNF325AE	—	2011~2012	2
TNF325AF	—	2011	1
TNF325AG	—	2012	1
TNF325AH	—	2012	6
TNF325AJ	—	2012	2
TNF325AK	—	2012	1
TNF326AA	—	2011	2
TNF326AB	—	2011~2012	3
TNF328AA	—	2010	3
TNF328AB	—	2010	2
TNF328AC	—	2011	1
TOTAL			33