VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	gai-1941	DATE	04, 07, 2013
MANUFACTURE	RENAULT SAS		
	(Japanese Importer : Ren	ault Japon Co., Ltd.)	
DESCRIPTION OF	Possibility of stalling of the engine during the shifting of the 1st gear to 2nd gear in automatic mode by poor calibration of the gearbox computer.		
DEFECT			

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-KWK4M	「KANGOO」	2009-2013	4478
		TOTAL	4478