

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	3183	DATE	Jul.2.2013
MANUFACTURER	Hino Motors, Ltd.		
DESCRIPTION OF DEFECT	<p>On certain heavy duty trailer tractors equipped with 12 speed transmission, since the surface hardness of the flange coupling end of a transmission is insufficient, the flange coupling end is worn out in connection with the creep of a bearing, and there are some in which the flange coupling fastening bolts loosens. If the vehicle is operated under the condition continuously, the flange coupling slip out, in the worst case, there is a possibility that the propeller shaft may come off the vehicle.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
KS-SH1EFJG	[HINO Profia]	2004	3
ADG-SH1EFXG		2006~2009	11
BDG-SH1EFXG		2007~2010	20
BDG-SH1EGXG			
BDG-SH1EGXGKAI			
		TOTAL	34