

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	Gai-1991	DATE	November 29, 2013
MANUFACTURER	Chrysler Group LLC (Japanese Importer : Chrysler Japan Co., Ltd.)		
DESCRIPTION OF DEFECT	The fuel tank transfer tube of the vehicles concerned may have been incorrectly manufactured. When the fuel transfer process becomes interrupted the vehicle is only operating on fuel from the primary side of the fuel tank. Sustained driving during this condition will deplete the fuel in the primary side of the fuel tank while fuel remains in the secondary side of the fuel tank. This could cause the engine to stall without warning under certain driving conditions.		

[illegible]