

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3 2 6 8	DATE	Nov. 27 .2013
MANUFACTURER	N I S S A N		
DESCRIPTION OF DEFECT	<p>On the ambulance vehicle, due to inappropriate operation instruction of the battery cable for the starter motor, the battery cable may be had a damage for it interface with the engine. If the vehicle continues to be driven in this condition, the battery cable may cause a short circuit. In an extreme case, the engine may stall and cannot be restarted.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
CBF-FPWGE50	「PARAMEDIC」	2013	14
		TOTAL	14