

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN NO.	3273	DATE	December 12 ,2013
MANUFACTURER		ISUZU MOTORS LIMITED	
DESCRIPTION OF DEFECT		On certain medium duty buses, as the label which displays the initial inclination designated value of cutoff (section line of light and shade of the light used in adjusting the radiation's direction) of irradiation light of low beam-headlight is not attached, the safety regulations of Road Vehicles Act are not conformed.	

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
SDG-RR7JJCJ	[ISUZU GALA MIO]	2011-2013	290
		TOTAL	290