

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	3272	DATE	Dec.12.2013
MANUFACTURER	Hino Motors, Ltd.		
DESCRIPTION OF DEFECT	On certain medium duty buses, as the label which displays the initial inclination designated value of cutoff (section line of light and shade of the light used in adjusting the radiation's direction) of irradiation light of low beam-headlight is not attached, the safety regulations of Road Vehicles Act are not conformed.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
SDG-RR7JJCA	[HINO Melpha]	2011~2013	385
SDG-RR7JJCAKAI			
		TOTAL	385