VEHICLES SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN



CAMPAIGN No.	Gai-2053	DATE	June 13.2014		
MANUFACTURER	YANMAR CO.,LTD.	•			
DESCRIPTION OF DEFECT	Because the structure was improper, the exhaust pipe damages. When continuing use in this condition, there is a fear that the emission of exhaust gas exceeds a standard value.				

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED		NUMBER OF VEHICLE
_	「JD-6170R」	2012~2013		6
_	「JD-6190R」	2012~2013		4
-	「JD-6210R」	2013		5
			TOTAL	15