

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN NO.	3396	DATE	July 24 ,2014
MANUFACTURER	ISUZU MOTORS LIMITED		
DESCRIPTION OF DEFECT	<p>Among the air suspension-equipped heavy-duty trucks, there are some of which V-rod bush to fix the rear axle to the frame, is inadequate and the snap ring bracing the bush comes off. If the truck is kept in operation under such a condition, the bush gets worn and the V-rod gets damaged. And as the result, the running stability of the truck may become impaired in the worst case scenario.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
LKG-CXY77AJ	[GIGA]	2010-2011	40	
PDG-CXY77Q8J PKG-CXY77Q8J		2009-2010	8	
PDG-CXY77S8J PKG-CXY77S8J		2009-2010	9	
PDG-CXY77V8J PKG-CXY77V8J		2009-2010	17	
PDG-CYJ52W8 PDG-CYJ52W8A		2009-2010	22	
LKG-CYJ77A LKG-CYJ77AA		2010-2011	2,292	
LKG-CYJ77AL		2010-2011	21	
LKG-CYJ77AZ		2010-2011	13	
PDG-CYJ77W8 PDG-CYJ77W8A PKG-CYJ77W8 PKG-CYJ77W8A		2009-2010	2,159	
PDG-CYJ77W8L PKG-CYJ77W8L		2009-2010	19	
PDG-CYJ77W8Z PKG-CYJ77W8Z		2009-2010	21	
LKG-CYY77AJ		2010-2011	25	
LKG-CYY77AY		2010-2011	139	
PDG-CYY77Q8J PKG-CYY77Q8J		2009-2010	15	
PDG-CYY77S8J PKG-CYY77S8J		2009-2010	4	
PDG-CYY77V8J PKG-CYY77V8J		2009-2010	431	
		TOTAL	5,235	

Vehicles Which Had The Affected Parts Installed After They Rolled Off The Assembly Line

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
PJ-CXG51X5	[GIGA]	2005	1
KL-CXY23Q3J		2000-2003	2
KL-CXY23S3J		2002	2
KL-CXY23V3J		2002	2
KL-CXY23V4J		2003	2
KL-CXY51Q3J		2002	1
KL-CXY51Q4J		2003	1
KL-CXY51S3J		2002	1
KL-CXY51V3J		2000-2002	4
PJ-CXY77S6J		2006	1
PDG-CXY77V8J		2007	1
PJ-CYG51Y5Z		2004	1
KC-CYH50W2W		1997	2
KL-CYJ23W3 KL-CYJ23W3A		2000-2003	26
KL-CYJ23W3Z		2000-2002	3
KL-CYJ23W4		2003-2004	9
KC-CYJ50W2		1997-2000	125
KL-CYJ51W3 KL-CYJ51W3A		2000-2003	331
KL-CYJ51W3Z		2000-2003	34
KL-CYJ51W4 KL-CYJ51W4A		2003-2005	117
KL-CYJ51W4Z		2003-2004	2
PJ-CYJ51W5 PJ-CYJ51W5A		2003-2005	116
PJ-CYJ51W5L		2005	2
PJ-CYJ51W6 PJ-CYJ51W6A		2005-2007	88
PJ-CYJ51W6Z		2005-2006	2
KL-CYJ52V3		2002	1
KL-CYJ52W3 KL-CYJ52W3A		2000-2003	12
KL-CYJ52W4 KL-CYJ52W4A		2003-2004	2
PJ-CYJ52W6 PJ-CYJ52W6A		2006	3
PDG-CYJ52W8		2008	1

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
PJ-CYJ77W6	[GIGA]	2005-2007	12
ADG-CYJ77W7 ADG-CYJ77W7A		2006-2007	12
PDG-CYJ77W8 PDG-CYJ77W8A PKG-CYJ77W8 PKG-CYJ77W8A		2007-2009	48
KC-CYJ81W2		1998-2000	9
KC-CYL23Q2		1997	1
KL-CYL23Q3		2000-2003	16
KL-CYL23Q4		2003-2005	16
KL-CYL23R3		2001	1
KL-CYL23T4		2003	1
KC-CYL23V2W		1998-1999	7
KL-CYL23V3 KL-CYL23V3A		2000-2003	4
KL-CYL23V3W		2000-2003	18
KL-CYL23V3Z		2000-2002	4
KL-CYL23V4		2003-2005	16
KL-CYL23V4Z		2003	2
KC-CYL50T2		1998-1999	2
KC-CYL50V2		1997-1999	52
KC-CYL50V2W		1997-1999	103
KC-CYL50V2Z		1997-1999	6
KL-CYL51Q3		2000-2003	9
PJ-CYL51Q6		2005	2
KL-CYL51T3		2000-2001	3
KC-CYL51V2		1999	7
KC-CYL51V2W		1999	16
KL-CYL51V3 KL-CYL51V3A		1999-2003	152
KL-CYL51V3W KL-CYL51V3WA		1999-2003	234
KL-CYL51V3Z		1999-2002	22
KL-CYL51V4 KL-CYL51V4A		2003-2005	186
KL-CYL51V4Z		2003-2004	7
PJ-CYL51V5 PJ-CYL51V5A		2003-2005	168

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
PJ-CYL51V5Z	[GIGA]	2004	4
PJ-CYL51V6 PJ-CYL51V6A		2005-2007	133
KL-CYL52V3 KL-CYL52V3A		2000-2003	23
KL-CYL52V3W KL-CYL52V3WA		2000-2003	12
KL-CYL52V4 KL-CYL52V4A		2003-2005	20
PJ-CYL52V6		2005-2006	5
PDG-CYL52V8		2007	2
PJ-CYL77Q6		2005-2007	6
PJ-CYL77V6		2005-2007	9
ADG-CYL77V7		2007	1
PDG-CYL77V8 PKG-CYL77V8		2007-2008	4
KC-CYL81Q2		1997-1998	2
KL-CYL81Q3		2000	1
KC-CYL81T2		1997-1998	2
KC-CYL81V2		1997-1999	10
KC-CYL81V2W		1997-1999	17
KC-CYL81V2Z		1998-1999	3
KC-CYM50V2W		1997	4
KC-CYM81V2W		1997	2
KL-CYY23Q4J		2004	1
KL-CYY23V3J		2003	1
KL-CYY23V4J		2003	4
KL-CYY51Q3J		2000-2001	3
KL-CYY51Q4J		2003	1
PJ-CYY51S5J		2004	2
KL-CYY51V3		2000-2003	13
KL-CYY51V3J		2000-2003	22
KL-CYY51V3W		2000-2002	10
KL-CYY51V3Z		2002	3
KL-CYY51V4		2003-2005	9
KL-CYY51V4J		2003-2005	7

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
KL-CYY51V4Z	[GIGA]	2003	1	
PJ-CYY51V5		2003-2005	11	
PJ-CYY51V5J		2003	1	
PJ-CYY51V5Z		2004	1	
PJ-CYY51V6		2005-2006	7	
KL-CYY52V3		2001-2002	5	
KL-CYY52V3W		2000-2002	4	
KL-CYY52V4		2003-2005	9	
PJ-CYY77Q6J		2006	2	
PJ-CYY77V6J		2007	1	
KL-EXD51D3		2003	1	
KL-EXD51G3		2003	1	
KC-EXD52D2		1997-1999	4	
KL-EXD52D3		2000-2005	26	
KC-EXD52E2		1997	1	
KL-EXD52E3		2001-2004	4	
KL-EXY52J3W		2005	1	
PJ-EXY52J6		2005	3	
		TOTAL	2,450	

The Affected Parts Shipped As Repair Parts, But The Vehicles With Them Installed, Cannot Be Identified.

PARTS NAME	PARTS NO.	SHIPMENT YEAR	NUMBER OF PARTS
V ROD ASSEMBLY	1-51510770-1	2009-2011	66
V ROD BUSH	1-51519159-1	2009-2010	586
		TOTAL	652