VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Q omestic	/Iron out	Valaialaa
Comesuc		venicies

Campaign No.	3380	Date	July 10, 2014
Manufacture	Caterpillar Japan LTI	D	
Description of Deffect	A fuel tube on engine may be fractured by fuel pressure pulsations. The tube may be fractureed. Then the fuel may leak.		

TYPE	COMMERCIAL	MODEL YEAR	NUMBER OF
1112	NAME	RECALLED	VEHICLE
JDS-MCC	「938H」	2009-2014	148
		TOTAL	148