

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	3419	DATE	Aug.26.2014
MANUFACTURER	Hino Motors, Ltd.		
DESCRIPTION OF DEFECT	On certain route buses with synthetic voice door open/close announce system, the control program for the said system is improper so that the "door open" announcement may not be issued when a driver sets the mid-door switch to "open" position for passengers to get in/out of the bus.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
BDG-HR7JPBE	[HINO Rainbow]	2008~2010	2
BJG-HU8JLFP	[HINO Blue Ribbon City]	2008~2010	105
LJG-HU8JLGP		2010~2014	51
LNG-HU8JLGP			
LNG-HU8JLGPKAI			
BJG-HU8JMFP		2008~2010	9
LJG-HU8JMGP		2010~2014	21
LNG-HU8JMGP			
BDG-HX6JLAE		[HINO Poncho]	2009~2011
SKG-HX9JHBE	2012		5
SDG-HX9JLBE	2011~2014		82
SKG-HX9JLBE			
SKG-HX9JLBEKAI			
BDG-RX6JFBA	[HINO Liesse]	2011	13
PDG-KR234J2	[HINO Rainbow II]	2008~2011	81
SDG-KR290J1		2011~2014	111
SKG-KR290J1			
PKG-KV234L2	[HINO Blue Ribbon II]	2008~2010	11
LKG-KV234L3		2011~2014	139
QDG-KV234L3			
QKG-KV234L3			
QPG-KV234L3			
PDG-KV234N2		2008~2010	13
PKG-KV234N2			
LKG-KV234N3		2011~2014	71
LKG-KV234N3KAI			
QKG-KV234N3			
QPG-KV234N3			
QPG-KV234N3KAI			
PDG-KV234Q2		2008~2010	9
PKG-KV234Q2			
LKG-KV234Q3		2011~2014	46
LKG-KV234Q3KAI			
QKG-KV234Q3			
QKG-KV234Q3KAI			
QPG-KV234Q3			
		TOTAL	779