

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

Campaign No.	Gai-2091	Date	25th Sep. 2014
Manufacture	Caterpillar Inc. (Caterpillar Japan LTD.)		
Description of Deffect	There is interference between steering hose and another system hose. The interference brings worn to boths hoses and it may cause breakage. And, it may bring steering control lost.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
EDR-JTM	「924H」	2011	6
		TOTAL	6