

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

Campaign No.	Gai-2090	Date	25th Sep. 2014
Manufacture	Caterpillar Inc. (Caterpillar Japan LTD.)		
Description of Deffect	The wheel mounting bolts may come loose. The wheel mounting bolts coming loose could result in the wheels separation from the machine.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
EDR-FTD	「930H」	2012-2013	42
		TOTAL	42