

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3454	DATE	Oct.24 2014
MANUFACTURER	KATO WORKS CO.,LTD.		
DESCRIPTION OF DEFECT	For the brake system in the pneumatic circuit, it was found that vehicles fitted with a hose which has some fittings improperly processed have been delivered, then, in case that you continue to use them for a long period, you might have rust on the fittings that could be caught in pneumatic valves, at worst, you might have air – leakage and insufficient braking force.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	Note
KRC014	KRM - 20H	2014	15	
		TOTAL	15	