

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	gai-2121	DATE	Dec 02, 2014
MANUFACTURE	RENAULT SAS (Japanese Importer : Renault Japon Co., Ltd.)		
DESCRIPTION OF DEFECT	Fuel hose may have been fitted the wrong way round on the production line therefore , abnormal wear of the fuel hose due to the contact with the air conditioning pipe.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-KWK4M	「KANGOO」	2012-2014	1951
		TOTAL	1951