

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	gai-2122	DATE	Dec 02, 2014
MANUFACTURE	RENAULT SAS (Japanese Importer : Renault Japon Co., Ltd.)		
DESCRIPTION OF DEFECT	Brake pipe may have been fitted the wrong way on the ABS hydraulic unit round on the production line therefore , cannot get the driving stability under heavy braking.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-KWK4M	「KANGOO」	2012-2013	858
		TOTAL	858