

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	Gai-2131	DATE	2014/12/25
MANUFACTURER	Chrysler Group LLC ( Japanese Importer : Chrysler Japan Co., Ltd. )		
DESCRIPTION OF DEFECT	The rear turn signal lamp outage detection on vehicles may not alert the vehicle operator of an inoperable turn signal. As a result, these vehicles fail to conform to the requirements of Economic Commission for Europe (ECE) Regulation 48. Undetected loss of turn signal operation could cause a crash under certain driving situations.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
ABA-WK36T	Jeep Grand Cherokee	2014	447
ABA-WK36TA	Jeep Grand Cherokee	2014	494
ABA-WK57A	Jeep Grand Cherokee	2014	54
-WK57A-	Jeep Grand Cherokee	2014	122
		Total	1,117