

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

| | | | |
|-----------------------|---|------|------------|
| CAMPAIGN No. | Gai-2133 | DATE | 2014/12/25 |
| MANUFACTURER | Chrysler Group LLC (Japanese Importer : Chrysler Japan Co., Ltd.) | | |
| DESCRIPTION OF DEFECT | Some Jeep Grand Cherokee may experience a hard brake pedal feel during certain braking events. The Anti-lock Brake System contains out-of-specification Traction Control Isolation Valve bores that are activated during Ready Alert Braking applications. The tapered Traction Control Isolation valve bores result in a reduced flow of fluid, when combined with the brake system pre-fill can result in a hard pedal sensation to the operator. | | |

| TYPE | COMMERCIAL NAME | MODEL YEAR RECALLED | NUMBER OF VEHICLES |
|-----------|---------------------|---------------------|--------------------|
| ABA-WK36 | Jeep Grand Cherokee | 2012 - 2013 | 92 |
| ABA-WK36A | Jeep Grand Cherokee | 2012 | 94 |
| ABA-WK57A | Jeep Grand Cherokee | 2012 | 1 |
| | | Total | 187 |