

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3497	DATE	Jan, 13, 2015
MANUFACTURER	KUBOTA Corporation		
DESCRIPTION OF DEFECT	The circlip of front axle for agricultural tractor may be misassembled. It leads to oil leakage, and the front axle may be come off at the worst.		
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
WDR-MGF	「M100G」	2014~2014	9
	「GR100G」	2014~2014	3
	「M110G」	2014~2014	63
	「GR110G」	2014~2014	12
WDR-MGY	「M115G」	2014~2014	20
	「GR115G」	2014	1
	「M125G」	2014~2014	27
	「GR125G」	2014	1
	「M135G」	2014~2014	54
	「GR135G」	2014	1
KDP-MZZ	「SMZ805」	2014~2014	102
	「GV805」	2014~2014	3
	「SMZ875」	2014~2014	57
	「SMZ955」	2014~2014	149
	「GV955」	2014~2014	27
		TOTAL	529