VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3552	DATE	Apr, 24, 2015
MANUFACTURER	KUBOTA Corporation		
DESCRIPTION OF DEFECT	The circlip of front axle for agricultural tractor may be misassembled. It leads to oil leakage, and the front axle may be come off at the worst.		
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
WDR-MGF	「M100G」	2014	23
	「M110G」	2013~2014	44
	「GR110G」	2014	3
WDR-MGY	「M115G」	2014	3
	「M125G」	2014	1
	「M135G」	2013~2014	23
KDP-MZZ	「SMZ805」	2013~2014	48
	「SMZ875」	2013~2014	27
	「GV875」	2014	1
	「SMZ955」	2013~2014	125
	「GV955」	2014	4
	•	TOTAL	302