

VEHICLE SAFETY/ POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicle

CAMPAIGN No.	3 5 5 8	DATE	Apr 21,2015
MANUFACTURER	TADANO LTD.		
DESCRIPTION OF DEFECT	<p>Due to inadequate strength of the parking brake chamber support on wheel crane braking devices, there is a chance of the support cracking.</p> <p>Therefore, with continued use in this condition, there is a risk of the support breaking resulting in a failure of the parking brake function.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
JDS-T006	TADANO 「GR-160N-2」 「GR-120NDW-2」	2008 — 2015	413
UDS-T009	TADANO 「GR-160N-3」	2013 — 2015	167
JDS-EW06	KOBELCO 「RK160-6」	2008 — 2013	61
UDS-EW07	KOBELCO 「RK160-7」	2014 — 2015	34
		TOTAL	675