

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3698	DATE	Nov.25 2015
MUNUFACTURER	Mitsubishi Fuso Truck and Bus Corporation		
DESCRIPTION OF DEFECT	On some heavy-duty regular-service buses with artificial-voice door open/close announcement system, the electrical wiring in the side switch box at the right side of the driver's seat is improper. This may cause failure of advance notice for opening/closing of the mid door.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
QKG-MP35FM	「FUSO AERO STAR」	2014~2015	3
QKG-MP38FK		2015	1
		TOTAL	4