

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN NO.	3707	DATE	DEC. 10, 2015
MANUFACTURER	MITSUBISHI MAHINDRA AGRICULTURAL MACHINERY CO.,LTD.		
DESCRIPTION OF DEFECT	<p>IN THE STRUCTURE OF THE TAIL LIGHTS AND THE STOP LIGHTS ON THE RELEVANT FARMING TRACTORS, WRONG PARTS WERE ASSEMBLED ON SOME VEHICLES DUE TO THE IMPROPER ASSEMBLY PROCESSES FOR THOSE LIGHTS.</p> <p>BECAUSE OF THIS, THE LIGHT DISTRIBUTION CHARACTERISTIC DOES NOT FULFILL THE TECHNICAL STANDARD AND ALSO DOES NOT CONFORM TO THE SAFETY STANDARD.</p>		
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
EDM-GT30F	「 GJ27D 」	2015 -2015	12
	「 GJ30D 」		11
		TOTAL	23