## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3736	DATE	Jan.26 2016			
MANUFACTURER	KATO WORKS CO.,LTD.					
DESCRIPTION OF DEFECT	Found that the model of the crane carrier below doesn't have the inrush prevention device which should be correctly designed and complied with the safety standards.					

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED		NUMBER OF VEHICLE	Note
KA5160	_	2015		3	
			TOTAL	3	