

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	Gai-2311	DATE	18. 02. 2016
MANUFACTURE	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	BMW Motorrad has ascertained that the flexibility of a front brake hose can be impaired if the positioning of the abrasion protection is poor. This can result in the brake hose suffering damage, which could subsequently lead to an escape of brake fluid. The stopping power of the front brake would diminish, depending on the amount of fluid lost in this way.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
C600S	BMW C600Sport	2012-2015	552
C650GT	BMW C650GT	2012-2015	736
		TOTAL	1,288