

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-2331	Date	April 20, 2016
MANUFACTURER	Volkswagen (Japanese Importer: Volkswagen Group Japan KK)		
DESCRIPTION OF DEFECT	Circlip, which prevents pedal shaft from coming off, might not be installed during brake pedal assembly manufacturing process. As a result, brake pedal shaft would come off the brake pedal bracket. In the worst case, brake will not work.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DAA-7PCGEA	VW Touareg V6 3.0 hybrid	MY2011-2014	592
DBA-7PCGRA	VW Touareg V6 3.6	MY2011-2016	147
DBA-7PCGRS			1,391
		Total	2,130