

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-2330	Date	April 20, 2016
MANUFACTURER	Volkswagen (Japanese Importer: Volkswagen Group Japan KK)		
DESCRIPTION OF DEFECT	Due to improper water drain design of high voltage battery store place in trunk room, water might remain in the store place if water entry occurs. As a result, water might enter to battery fan and it will cause short circuit in high voltage battery or short circuit in battery terminal, which lead to fire in the worst case.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DAA-7PCGEA	VW Touareg V6 3.0 hybrid	MY2011-2014	592
		Total	592