

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	gai-2353	DATE	Jul 14, 2016
MANUFACTURE	RENAULT SAS (Japanese Importer : Renault Japon Co., Ltd.)		
DESCRIPTION OF DEFECT	The risk of loss of the clutch function by incorrect push rod of the clutch transmitter on the axis of the clutch pedal.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-KWH5F	「KANGOO」	2015	21
		TOTAL	21