

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

~~Domestic~~ /Import Vehicles

CAMPAIGN No.	Gai-2322	DATE	05/September/2016
MANUFACTURER	Automobiles Volvo Car Corporation (Japanese Importer: Volvo Car Japan Limited)		
DESCRIPTION OF DEFECT	The turn Indicator lamp in Driver Information Module (DIM) flashes with a higher frequency than during a normal flashing and a text message displayed in DIM. To upgrade the CEM software.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
VOLVO	[S60]	2015—2016	786
	[V60]	2015—2016	1855
	[V60CC]	2016	618
		TOTAL	3259