

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

~~Domestic~~ Import Vehicles

CAMPAIGN No.	3903	DATE	Sep. 30. 2016
MANUFACTURER	Hino Motors, Ltd.		
DESCRIPTION OF DEFECT	On certain heavy duty trucks, due to the improper structure of the closed ventilator (crankcase emission control system) of the engine, there are some that the ventilator element becomes clogged before the periodic replacement. Therefore, the internal pressure of the crankcase rises and the engine oil flows into an intake system, which may cause the white smoke and the lack of power. In the worst case, an unintended increase in the engine speed will occur and the amount of the engine oil may be decreased, causing the engine to be damaged, resulting in a fire.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
QKG-FH1ANAG	[HINO Profia]	2012	1
LKG-FN1AWAA		2011~2012	4
QKG-FN1AWAG			
LKG-FN1AYBA		2010	1
QKG-FQ1EWBG		2013	1
LKG-FR1ANAA		2011	2
LKG-FR1APBG		2011	2
LKG-FR1AXBA		2010~2012	7
LKG-FR1AXBG			
QPG-FR1EPEA		2014	1
LKG-FR1EXBA		2010~2014	44
LKG-FR1EXBG			
LKG-FR1EXBGKAI			
LKG-FR1EXBJ			
QKG-FR1EXBA			
QKG-FR1EXBG			
QPG-FR1EXEA		2015	1
LKG-FR1EZBG		2010~2011	7
LKG-FR1EZBJ			
QPG-FR1EZEG		2014	1
LDG-FS1EKAA		2010~2014	9
LKG-FS1EKAA			
QKG-FS1EKAA			
QKG-FS1EKDA		2014~2015	3
QKG-FS1EPBA		2013	1
QKG-FS1EPEA		2014	2
QPG-FS1EPEA			
LDG-FS1ERBA		2010~2012	2
QDG-FS1ERBA			
QDG-FS1EREA		2015	1
QKG-FS1EWBA		2012	1
QKG-FS1EZBA		2013	1
LDG-FW1AXBG		2011~2012	9
LKG-FW1AXBG			
QKG-FW1AXBG			

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
LDG-FW1EWBAKAI	[HINO Profia]	2011	1
LDG-FW1EXBG		2010~2014	36
LKG-FW1EXBG			
QKG-FW1EXBG			
QPG-FW1EXEG		2014~2015	4
QPG-FW1EXEJ			
LKG-FW1EZBG		2010~2011	4
LKG-FW1EZBJ			
LKG-SH1EDAG		2010~2014	29
QKG-SH1EDAG			
QPG-SH1EDDG		2014~2015	3
QPG-SH1EDDJ			
LKG-SH1EEAG		2010~2011	2
QPG-SH1EEDG		2014	1
LKG-SH1EGAG		2011~2013	5
QKG-SH1EGAG			
LDG-SS1EKAA		2011~2014	4
QDG-SS1EKAA			
QKG-SS1EKAG			
QDG-SS1EKDA		2014	1
		TOTAL	191