## VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

 

 CAMPAIGN No.
 GAI-2371
 DATE
 November 30th, 2016

 MANUFACTURE
 PIAGGIO & C.s.p.a
 (Japanese Importer : PIAGGIO Group Japan Corporation )

 DESCRIPTION OF DEFECT
 Because shape of the Front brake master cylinder push rod is inappropriate, allows the incoming of air in the circuit. While using the brake repeatedly, it is possible that the braking distance increases.

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ZD4VK ZD4TY	「Caponord 1200ABS」 「TUONO V4 R APRC ABS」	2014 2013-2014	21 units 8 units
		TOTAL	29 units