

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

~~Domestic~~ /Import Vehicles

CAMPAIGN No.	Gai-2396	DATE	2/December/2016
MANUFACTURER	Automobiles Volvo Car Corporation (Japanese Importer: Volvo Car Japan Limited)		
DESCRIPTION OF DEFECT	Condensation water, transferred through the air conditioning drainage hose, may leak into the occupant compartment. The corrective action is to inspect the air conditioning drainage hose fixation and if necessary replace the drainage hose.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
VOLVO	[XC90]	2016 - 2017	525
TOTAL			525